OIPE 408

PTO/SB/17 (07-06)
Approved for use through 01/31/2007. OMB 0651-0032
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paren Reduction Act of 1995, no person are required to respond to a collection of information unless it displays a valid OMB control number Complete if Known Effective on 12/08/2004. Patent#: 7,133,307 Fees pursuant to the Consolidated Appropriations Act, 2005 (H.R. 4818). **Application Number** Issued: November 7, 2006 FEE TRANSMITTAL Filing Date R. Jacob Baker First Named Inventor For FY 2006 A. Q. Tran **Examiner Name** Applicant claims small entity status. See 37 CFR 1.27 2824 Art Unit M4065.0451/P451-B TOTAL AMOUNT OF PAYMENT 100.00 Attorney Docket No. METHOD OF PAYMENT (check all that apply) Money Order None Other (please identify): Check x Credit Card Deposit Account Deposit Account Number: 04-1073 Deposit Account Name: Dickstein Shapiro LLP For the above-identified deposit account, the Director is hereby authorized to: (check all that apply) Charge fee(s) indicated below, except for the filing fee Charge fee(s) indicated below Charge any additional fee(s) or underpayments of Credit any overpayments fee(s) under 37 CFR 1.16 and 1.17 **FEE CALCULATION** 1. BASIC FILING, SEARCH, AND EXAMINATION FEES **FILING FEES SEARCH FEES EXAMINATION FEES Small Entity Small Entity Small Entity** Fees Paid (\$) Fee (\$) Fee (\$) Application Type Fee (\$) Fee (\$) Fee (\$) Fee (\$) 500 200 100 Utility 300 150 250 Design 200 100 100 50 130 65 200 100 300 150 160 80 Plant 250 600 300 300 500 150 Reissue 0 200 100 0 Provisional **Small Entity** 2. EXCESS CLAIM FEES Fee (\$) Fee (\$) Fee Description 25 Each claim over 20 (including Reissues) 50 200 100 Each independent claim over 3 (including Reissues) 180 360 Multiple dependent claims Fee Paid (\$) **Multiple Dependent Claims Total Claims Extra Claims** Fee (\$) Fee Paid (\$) HP = highest number of total claims paid for, if greater than 20. Fee Paid (\$) Indep. Claims **Extra Claims** Fee (\$) HP = highest number of independent claims paid for, if greater than 3. 3. APPLICATION SIZE FEE If the specification and drawings exceed 100 sheets of paper (excluding electronically filed sequence or computer listings under 37 CFR 1.52(e)), the application size fee due is \$250 (\$125 for small entity) for each additional 50 sheets or fraction thereof. See 35 U.S.C. 41(a)(1)(G) and 37 CFR 1.16(s). Fee Paid (\$) **Extra Sheets** Number of each additional 50 or fraction thereof Fee (\$) - 100 = (round up to a whole number) x 4. OTHER FEE(S) Fees Paid (\$) Non-English Specification, \$130 fee (no small entity discount) 100.00 Other (e.g., late filing surcharge): 1811 Certificate of correction SUBMITTED BY Registration No. (Attorney/Agent) 28,371 Telephone (202) 420-2232 Signature Date November 28, 2006 Name (Print/Type) Thomas J. D'Amico

Certificate

DEC 0 1 2006

of Correction

50 0 4 2006



Docket No.: M4065.0451/P451-B

(PATENT)

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of:

R. Jacob Baker

Patent No.: 7,133,307

Issued: November 7, 2006

For: RESISTIVE MEMORY ELEMENT SENSING

USING AVERAGING

## REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.322 & 1.323

Attention: Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Sir:

Upon reviewing the above-identified patent, Patentee noted errors which should be corrected.

In the Specification, the PTO made the following errors to be corrected:

Column 3, line 63, "dock" should read --clock--;

Column 5, line 13, "dock" should read --clock--;

Column 5, line 57, "dock" should read --clocky/2005 SZEUDIE: 20222270 7133337

01 FG:1811

163.62 62

Column 5, line 62, "dock cycle of dock" should read --clock cycle of clock--;

0 4 LUU0

Patent No.: 7,133,307 Docket No.: M4065.0451/P451-B

Column 6, line 41, "dock" should read --clock--;

Column 6, line 42, "dock" should read --clock--; and

Column 6, line 56, "docked" should read --clocked--.

In Claim 9, Applicant's Rule 312 Amendment, filed July 19, 2006, inadvertently failed to include the following changes as mandated in the Examiner's Amendment of February 2, 2006:

Column 8, line 19, "reservoir" should read --storage device--;

Column 8, line 33, "reservoir" should read --storage device--;

Column 8, line 34, "reservoir" should read--storage device--; and

Column 8, line 35, "reservoir" should read --charge storage device--.

The errors were both found in the application as filed by applicant and made by the PTO. Please charge our Credit Card in the amount of \$100.00 covering the fee set forth in 37 CFR 1.20(a). Credit Card Payment Form SB-2038, with a signature from an authorized cardholder, is enclosed.

The errors now sought to be corrected are inadvertent errors the correction of which does not involve new matter or require reexamination.

Transmitted herewith is a proposed Certificate of Correction effecting such amendment. Patentee respectfully solicits the granting of the requested Certificate of Correction.

Patent No.: 7,133,307 Docket No.: M4065.0451/P451-B

The Director is hereby authorized to charge any deficiency in the fees filed, asserted to be filed or which should have been filed herewith (or with any paper hereafter filed in this application by this firm) to our Deposit Account No. 04-1073, under Order No. M4065.0451/P451-B.

Dated: November 28, 2006

Respectfully submitted,

Thomas J. D'Amico

Registration No.: 28,371

Rachael Lea Leventhal

Registration No.: 54,266 DICKSTEIN SHAPIRO LLP

1825 Eye Street, NW

Washington, DC 20006-5403

(202) 420-2200

Attorneys for Applicant

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page \_1\_ of \_1

PATENT NO.

7,133,307

APPLICATION NO. :

10/674,550

ISSUE DATE

November 7, 2006

INVENTOR

R. Jacob Baker

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Specification, the following errors are corrected:

Column 3, line 63, "dock" should read --clock--;

Column 5, line 13, "dock" should read --clock--;

Column 5, line 57, "dock" should read --clock--;

Column 5, line 62, "dock cycle of dock" should read --clock cycle of clock--;

Column 6, line 41, "dock" should read --clock--;

Column 6, line 42, "dock" should read --clock--; and

Column 6, line 56, "docked" should read --clocked--.

In Claim 9, the following errors are corrected:

Column 8, line 19, "reservoir" should read --storage device--;

Column 8, line 33, "reservoir" should read --storage device--;

Column 8, line 34, "reservoir" should read--storage device--; and

Column 8, line 35, "reservoir" should read --charge storage device--.

MAILING ADDRESS OF SENDER (Please do not use customer number below):